Sanitized Copy Approved for Release 2010/08/25 : CIA-RDP80T00246A038600340001-6

INFORMATION REPORT INFORMATION REPORT

CENTRAL INTELLIGENCE AGENCY

This material contains information affecting the National Defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C. Secs. 793 and 794, the transmission or revelation of which in any manner to an unauthorized perso 50X1-HUM by law.

	C-(-N-F-I-D-E-		CECCINIC CODY					
COUNTRY	Poland	REPORT	9.2001.10 051 1					
SUBJECT	Railroad Rolling Stock Repair Plant	DATE DISTR. 26 NOV 1	957					
	in Stargard Szczecinski / Manpower, Equipment , Security.	NO. PAGES		i				
		REQUIREMENT NO. RD						
DATE OF INFO.		REFERENCES		500/4 111184				
PLACE & DATE ACQ.				50X1-HUM				
DATE ACQ.	SOURCE EVALUATIONS ARE DEFINITIVE. APPRA	ISAL OF CONTENT IS TEN	ITATIVE.	4.000				
				50X1-HUM				
	A report containing marginal informatistick repair plant in Stargard Szczeci	on on a railroad ronski (N 53-20, E 15	lling -03) 50X1-HUM					
2.								
			50X1-HUM					
[50X1-HUM				
				30X1-HUM				

C-O-N-F-I-D-E-N-T-I-A-I,

STATE	#x	ARMY	#x.	NAVY	:8	AIR	¥/	.X.	FBI		AEC			
(Note: Washington distribution indicated by "X"; Field distribution by "#".)														

C-O-N-F-I-D-E-N-T-I-A-L

,		CONFID	50X1-HUM
COUNT	Y : Poland		
SUBJE	T : Railroad Rolling Stock Repair Plant in Stargard Szczecinski, Poland		
1.	The Railroad Rolling Stock Repair Plant (Zaklady Naprawcze Kolejowego) in Stargard Szczecinski (N 53-20, E 15-03) was plant which repaired locomotives, passenger and all types cars for the District Railroad Administration (Okregowa Dy Panstwowych) in Szczecin. It employed about 2,000 workers	a pre-war of freight rekcja Koleji	
•	seemed to be well-organized and equipped. It had all kind tools, including drilling, shaping, and grinding machines, types of small and large lathes; each of these was independentically driven.		
2.	an order on behalf of the shipyard for a hub. This hub, which was to be manufactured plant, was required for a three-and-one-half-ton ship screen measuring three meters in diameter. The order was complete	at the	
	The plant occupied a large fenced-in area, and all building workshops were of brick construction. It was guarded by an guards,		50X1-HUM

C-O-N-F-I-D-E-N-T-I-A-L

William